

The diagram shows a rectangular sheet metal part with a wavy edge. The overall dimensions are labeled as **Breite Width** (vertical) and **Länge Length** (horizontal). The part is divided into several regions by dashed lines and labels:

- 1**: The main body of the part.
- 2**: A horizontal strip at the top.
- 3 (1)**: A horizontal strip on the left side.
- 3 (2)**: A horizontal strip at the bottom.
- 4**: A vertical strip on the right side.
- 5**: A diagonal strip.
- 6 (1)**: A horizontal strip at the top right.
- 6 (2)**: A horizontal strip at the bottom right.

Key features and labels include:

- 1. Schnitt 1st Cut**: Indicated by a dashed line at the bottom left.
- 2. Schnitt 2nd Cut**: Indicated by a dashed line at the top left.
- 3. Schnitt 3rd Cut**: Indicated by a dashed line on the left side.
- Verbindungspunkt Connection Joint**: Indicated by a dashed line on the right side.
- Verschnitt Scraps**: Indicated by a dashed line at the bottom left.

Stich-, Kreissäge oder Teppichmesser.